GageXpress 3.7.1b11, Limit Color Functionality

Here is how you modify the colors:

1) Start Profile.

2) Click Preferences.3

3) Click Limit Colors.

4) Click the cell showing the color you want to change. There are options for changing the foreground and background colors for each limit. When you click the cell showing the current color, a color editor will appear allowing you to select a new color. Two tabs are available. One of measurement colors and one for part colors. The part colors are used to represent the part status on the part summary and recent history screens.

The Defaults button restores all color selections to defaults.